

Site Name: Wood Guard Lumber

EPA ID#: WD982572455 DSN: WV-576

Site Names: _____

ORIGINAL
(Red)

City: ANDERSON

County: MONROE

State: WV

Refer to Report Dated: 12-27-94

Report type: PA

Report developed by: WV DEP

DECISION:

X 1. Further Remedial Site Assessment under CERCLA (Superfund) is not required because:

☒ 1a. Site does not qualify for further remedial site assessment under CERCLA (Site Evaluation Accomplished - SEA) | 1b. Site may qualify for further action, but is deferred to: | RCRA | NRC

☐ 2. Further Assessment Needed Under CERCLA: 2a. (optional) Priority: | Higher | Lower

2b. Activity Type: | PA | SI | ESI | HRS evaluation | Other:

DISCUSSION/RATIONALE:

Wood Guard Lumber is a 5.81 acres Wood Treatment. The Wood Guard Lumber scored 8 based on limited targets

PA Decision: Based on the PA, EPA decided that the Wood Guard Lumber SITE receive No-Further-Action qualifier. If EPA receives new information regarding additional information, we evaluate the data and respond accordingly.

Report Reviewed: JAMES HARGETT JR
Approved by: Site Assessment Manager

Signature: [Signature] Date: 01/17/95

Decision: SAME
Made by: Site Assessment Manager

Signature: _____ Date: _____